

Visy Pulp and Paper Tumut CEMS - Correction Log

5/11/2021

Reporting Period: 1/10/2021 - 1/11/2021

Environment Protection Licence No: 10232

Main Stack 1

Monitoring Location No: 1
 Monitoring Type: Continuous
 Sample Type: Air
 Description: Exit point from Stack 1 to atmosphere

Opacity						Period: 6 Minutes	Limit: 20.00 %
Start Time	End Time	Cause	Operational State	Explanation	Max Reading		
01/10/21 12:42	01/10/21 12:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.09		
02/10/21 12:42	02/10/21 12:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.60		
03/10/21 13:42	03/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.76		
04/10/21 13:42	04/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.88		
05/10/21 13:42	05/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.05		
06/10/21 13:42	06/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.12		
07/10/21 13:42	07/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.66		
08/10/21 13:42	08/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.75		
09/10/21 13:42	09/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	24.34		
10/10/21 13:42	10/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	28.92		
11/10/21 13:42	11/10/21 13:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	23.44		
12/10/21 09:24	12/10/21 09:30	Recovery Boiler A	RB A Scheduled Start-up/Shut-down	MSD 2021 run down and start up of RBA LKA/B	27.03		
12/10/21 09:54	12/10/21 10:00	Recovery Boiler A	RB A Scheduled Start-up/Shut-down	MSD 2021 run down and start up of RBA LKA/B	28.53		
14/10/21 10:42	14/10/21 10:48	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.64		
18/10/21 09:54	18/10/21 10:06	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	69.99		
18/10/21 14:48	18/10/21 14:54	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	31.13		
18/10/21 15:42	18/10/21 15:48	Recovery Boiler A	RB A Scheduled Start-up/Shut-down	MSD 2021 run down and start up of RBA LKA/B	54.26		
18/10/21 17:00	18/10/21 17:06	Recovery Boiler A	RB A Scheduled Start-up/Shut-down	MSD 2021 run down and start up of RBA LKA/B	31.51		

19/10/21 07:18	19/10/21 07:30	Recovery Boiler A	RB A Scheduled Start-up/Shut-down	MSD 2021 run down and start up of RBA LKA/B	22.82
19/10/21 15:30	19/10/21 15:36	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.42
23/10/21 18:36	23/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.78
24/10/21 18:36	24/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.14
25/10/21 18:36	25/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	20.66
26/10/21 18:36	26/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.21
27/10/21 18:36	27/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.38
28/10/21 18:36	28/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.46
29/10/21 18:36	29/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	21.99
30/10/21 18:36	30/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.61
31/10/21 18:36	31/10/21 18:42	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	22.82

Authorised By:

Uday Bhagwat
Pulp Mill Manager


2-11-21

Johan Stoltz
General Manager

