

## Main Stack 1

Monitoring Location No: 1  
 Monitoring Type: Continuous  
 Sample Type: Air  
 Description: Exit point from Stack 1 to atmosphere

| Opacity        |                | Period: 6 Minutes           | Limit: 20.00 %        |                  |             |  |
|----------------|----------------|-----------------------------|-----------------------|------------------|-------------|--|
| Start Time     | End Time       | Cause                       | Operational State     | Explanation      | Max Reading |  |
| 02/09/22 16:18 | 02/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.38       |  |
| 03/09/22 16:18 | 03/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.71       |  |
| 04/09/22 16:18 | 04/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.93       |  |
| 05/09/22 16:18 | 05/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.91       |  |
| 06/09/22 16:18 | 06/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.70       |  |
| 07/09/22 16:18 | 07/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.49       |  |
| 08/09/22 16:18 | 08/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.57       |  |
| 09/09/22 16:18 | 09/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.82       |  |
| 10/09/22 16:18 | 10/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.63       |  |
| 11/09/22 16:18 | 11/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.62       |  |
| 12/09/22 16:18 | 12/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.06       |  |
| 13/09/22 16:18 | 13/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.98       |  |
| 14/09/22 16:18 | 14/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.91       |  |
| 15/09/22 16:18 | 15/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.10       |  |
| 16/09/22 09:30 | 16/09/22 09:36 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 32.26       |  |
| 16/09/22 16:18 | 16/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 22.32       |  |
| 17/09/22 16:18 | 17/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.69       |  |
| 18/09/22 16:18 | 18/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.61       |  |

|                |                |                             |                       |                  |       |
|----------------|----------------|-----------------------------|-----------------------|------------------|-------|
| 19/09/22 16:18 | 19/09/22 16:24 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 23.50 |
| 26/09/22 16:12 | 26/09/22 16:18 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.84 |
| 27/09/22 16:12 | 27/09/22 16:18 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.89 |
| 28/09/22 16:12 | 28/09/22 16:18 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 20.70 |
| 29/09/22 16:12 | 29/09/22 16:18 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.13 |
| 30/09/22 16:12 | 30/09/22 16:18 | Auto Zero Span Verification | Normal (Steady State) | Auto Calibration | 21.61 |

Authorised By:

**Uday Bhagwat**  
Pulp Mill Manager



**Johan Stoltz**  
General Manager

